

## ME3: Flash erase



Do not sent the "ME3\_flash\_erase.fw" to customer, it is a special version for service purposes only.

The reason why the ME is not working anymore is because of a corrupted ME memory during the firmware update. The "ME3\_flash\_erase.fw" will clear the ME memory after updating.

### GX1200

- Copy the "ME3\_flash\_erase.fw" into the system folder on the CF-Card
- Insert the CF-Card into the GX1200 and load the ME-Firmware  
6 Tools.. → 3 Upload System Files... → 3 Instrument Firmware
- After a successful firmware loading reboot the sensor
- Load the ME3GG firmware 3.019 again

### ATX1230GG/ATX900 GG

- Load the "ME3\_flash\_erase.fw" via service software
- Load the ME3GG firmware 3.019 again via service software
- Set the instrument type again



When the "ME3\_flash\_erase.fw" is loaded, the instrument is not able to track satellites. Therefore its needed to load the ME3GG firmware 3.019 again.